



NEW TRASDATA (JTAG/BDM/BOOT) ECU APPLICATION LIST

Release D/16 (01/07/2016) referred to SW: 3.0.54 DLL: 1.0.165 FW: 8.001 build 0001

DIMSPORT Srl Località San Iorio 8B, Zona Industriale Madonna 15020 Serralunga di Crea (AL) ITALY T +3901429552 F +390142940094

http://www.dimsport.it sales dept: info.race@dimsport.it; tech dept: support.race@dimsport.it

This application list is merely indicative. Dimsport Srl reserves the right to modify the list without any notice and at any time.

La presente lista ha carattere meramente indicativo. Dimsport Srl si riserva il diritto di apportare modifiche in qualunque momento e senza preavviso.

IMPORTANT WARNING

Starting from TOS (Trasdata Operative System) firmware version 8.0, NewTrasdata Master&Slave will require a mandatory internet connection for reading and writing procedures.

The connections and the full functionality of the system will be guaranteed to all tools, regardless of subscription expiry date and plug-in families enabled.

A partire dalla versione firmware 8.0 del TOS (Trasdata Operative System), gli strumenti NewTrasdata Master&Slave richiederanno la connessione Internet obbligatoria per operazioni di lettura e scrittura.

Lo stato degli abbonamenti o delle abilitazioni NON influisce sulla connessione alla rete Internet: il funzionamento del sistema (sia software sia hardware) non cambierà in nessuna delle sue specifiche.

CPU SUPPORTED (GROUPS AND FAMILIES) / CPU SUPPORTATE (GRUPPI E SOTTOFAMIGLIE)

New/ Upg	GROUP ID	CPU GROUP / GRUPPO CPU	CPU FAMILIES INCLUDED IN THE GROUP / FAMIGLIE CPU INCLUSE NEL GRUPPO
	TF001	MOTOROLA MPC55X/MPC56X CPU group	-> 01 - MOTOROLA MPC55X/MPC56X (TM001)
Upg	TF002	STMICROELECTRONICS ST10 CPU group	-> 02 - STMICROELECTRONICS ST10 (TM002) -> 05 - SPECIAL ST10 (TM005)
Upg	TF003	INFINEON TRICORE CPU group	-> 03 - INFINEON TRICORE NO PSW (TM003) -> 04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004) -> 11 - INFINEON TRICORE SIEMENS SD16 PORSCHE (TM011) -> 12 - INFINEON TRICORE BOSCH EDC17 TPROT8 BMW (TM012) -> 13 - INFINEON TRICORE BOSCH MEDC17 TPROT8/10 VAG (TM013) -> 14 - INFINEON TRICORE NO PSW KLINE (TM014) -> 15 - INFINEON TRICORE BOSCH EDC17 TPROT11 FAL (TM015) -> 16 - INFINEON TRICORE FOMOCO SID208/SID807 (TM016) -> 18 - INFINEON TRICORE SIEMENS PCR2.1/SIMOS8.xx VAG (TM018) -> 19 - INFINEON TRICORE BOSCH MEDC17 TPROT11 KIA/HYUNDAI (TM019) -> 20 - INFINEON TRICORE BOSCH MEDC17 TPROT12 FORD (TM020) -> 22 - INFINEON TRICORE BOSCH MEDC17 GPT BMW (TM022) -> 23 - INFINEON TRICORE BOSCH MEDC17 GPT VAG (TM023) -> 24 - INFINEON TRICORE BOSCH MEDC17 GPT VOLVO (TM024) -> 25 - INFINEON TRICORE BOSCH MEDC17 GPT JAGUAR/LAND ROVER (TM025) -> 26 - INFINEON TRICORE BOSCH MEDC17 GPT OPEL (TM026) -> 27 - INFINEON TRICORE BOSCH MEDC17 GPT MERCEDES (TM027) -> 28 - INFINEON TRICORE BOSCH MEDC17 GPT FORD (TM028) -> 29 - INFINEON TRICORE BOSCH MEDC17 GPT FCA (TM029) -> 30 - INFINEON TRICORE BOSCH MEDC17 GPT MCLAREN (TM030) -> 31 - INFINEON TRICORE BOSCH MEDC17 GPT RENAULT (TM031) -> 32 - INFINEON TRICORE BOSCH MEDC17 GPT NISSAN (TM032) -> 33 - INFINEON TRICORE BOSCH MEDC17 GPT ASTON MARTIN (TM033) -> 34 - INFINEON TRICORE BOSCH MEDC17 GPT PSA (TM034) -> 35 - INFINEON TRICORE BOSCH MEDC17 GPT HONDA (TM035) -> 38 - INFINEON TRICORE BOSCH MED17 GPT DUCATI (TM038) -> 39 - INFINEON TRICORE BOSCH MEDC17 GPT TOYOTA (TM039) -> 41 - INFINEON TRICORE BOSCH MEDC17 GPT HYUNDAI/KIA (TM041)
Upg	TF004	MOTOROLA MPC55xx CPU group	-> 06 - NEXUS MOTOROLA MPC55xx (TM006)
Upg	TF005	RENESAS SH7050 CPU group	-> 07 - RENESAS SH7050 (TM007)
Upg	TF006	MITSUBISHI MH7xxx/MH8xxxx CPU group	-> 08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)
Upg	TF007	MOTOROLA MC68xxx CPU group	-> 09 - MOTOROLA MC68xxx (TM009)
Upg	TF008	MOTOROLA HC12 CPU group	-> 10 - MOTOROLA HC12 (TM010)
Upg	TF009	RENESAS M32R CPU group	-> 17 - RENESAS M32R (TM017)
Upg	TF010	NEC 76F00xx NBD CPU group	-> 36 - NEC 76F00xx NBD (TM036) NEC76F0038GD NEC76F0038AGD NEC76F0039GD NEC76F0039AGD NEC76F0040GD NEC76F0040AGD NEC76F0070 NEC76F0085

ECU SUPPORTED / CENTRALINE SUPPORTATE

PLUGIN ID	VEHICLE MANUFACTURER / COSTRUTTORE	ECU BRAND / MARCA ECU	ECU MODEL / MODELLO ECU	CPU (PROCESSOR) / CPU (PROCESSORE)	CPU GROUP / GRUPPO CPU	CPU APPLICATION (SPEC.) / FAMIGLIA CPU (SPEC.)	OBDDII PATCH / SBLOCCO OBDDII	CHECKSUM MOD. / MOD. CHECKSUM
383	Agrale Cargo Truck	Bosch	EDC17C1	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E52
545	Agrale Cargo Truck	Bosch	EDC7UC31	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
94	Aprilia / Piaggio	IAW Marelli	SDM	ST10F296	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
239	Aprilia / Piaggio	IAW Marelli	ZSM	ST10F296	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
727	Aston Martin	Bosch	ME17.8.31	TC1797	TF003	33 - INFINEON TRICORE BOSCH MEDC17 GPT ASTON MARTIN		E94
424	Aston Martin	FoMoCo	PCM150x	MPC565 / MPC566	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E117
721	Avia Truck	Continental	CM2150E	MPC5566	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		NO CHECKSUM
613	Bentley	Bosch	ME7.1.1	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E84
649	Bmc Cummins Engines	Motorola	CM850	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		NO CHECKSUM
3	Bmw	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E52
100	Bmw	Bosch	EDC16+	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
220	Bmw	Bosch	EDC17C41	TC1797	TF003	12 - INFINEON TRICORE BOSCH EDC17 TPROT8 BMW (TM012)		E94
666	Bmw	Bosch	EDC17C41 GPT (F series)	TC1797	TF003	22 - INFINEON TRICORE BOSCH EDC17 GPT BMW		E94
221	Bmw	Bosch	EDC17C45	TC1797	TF003	12 - INFINEON TRICORE BOSCH EDC17 TPROT8 BMW (TM012)		E94
670	Bmw	Bosch	EDC17C56	TC1797	TF003	22 - INFINEON TRICORE BOSCH EDC17 GPT BMW		E94
154	Bmw	Bosch	EDC17CP02	TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
156	Bmw	Bosch	EDC17CP09 external flash	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
667	Bmw	Bosch	EDC17CP45 GPT (F series)	TC1797	TF003	22 - INFINEON TRICORE BOSCH EDC17 GPT BMW		E94
671	Bmw	Bosch	EDC17CP49	TC1797	TF003	22 - INFINEON TRICORE BOSCH EDC17 GPT BMW		E94
668	Bmw	Bosch	EDC17CP50/EDC17CP56 GPT (F series)	TC1797	TF003	22 - INFINEON TRICORE BOSCH EDC17 GPT BMW		E94
452	Bmw / Bmw Motorrad	Bosch	ME17.2 BMSX	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
604	Bmw	Bosch	ME7.2	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E19
19	Bmw	Bosch	ME9	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E75
229	Bmw	Bosch	ME9 2xDE28F800F3	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E75
103	Bmw	Bosch	ME9+	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E75
163	Bmw	Bosch	ME9+	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E75
679	Bmw	Bosch	MEDV17.2.5/MEDV17.2.8/MEDV17.2.9	TC1797	TF003	22 - INFINEON TRICORE BOSCH EDC17 GPT BMW		E94
171	Bmw	Bosch	MEV1746	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
215	Bmw	Bosch	MEVD17.2	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
678	Bmw	Bosch	MEVD17.2.G/MEDV17.2.6	TC1797	TF003	22 - INFINEON TRICORE BOSCH EDC17 GPT BMW		E94
18	Bmw	Siemens	MS45.0	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E77
117	Bmw	Siemens	MSS 60 - MSS 65 #L	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E86
116	Bmw	Siemens	MSS 60 - MSS 65 #R	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E86
110	Bmw	Siemens	MSV70 / MSS70	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E78
65	Bmw / Mini	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
148	Bmw / Mini / PSA Group	Bosch	MED17.2/MEV17.2 (ext. Flash)	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
516	Bmw / Mini / PSA Group	Bosch	MEVD17.2.7	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
485	Bmw / Yanmar	Bosch	EDC16C1-4.41	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E52
136	Bmw Motorrad	Bosch	ME9 BMSK	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E95
188	Bmw Motorrad	Bosch	ME9+ BMSK	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E75/E95
552	Brp	Continental Siemens VDO	M3C S12XET256MAL	MC9S12XE256	TF008	10 - MOTOROLA HC12 (TM010)		E115
536	Bugatti	Bosch	ME9.1.1	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E141
124	Case (Cummins)	Motorola	CM850	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		NO CHECKSUM
467	Case / New Holland	Bosch	EDC17C49	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94/E145
392	Caterham	MBE	958	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		NO CHECKSUM
704	Caterpillar	CAT	ASM8	MPC5566	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		
440	Caterpillar	Caterpillar	Adem III (AT25160 eeprom)	MC68300	TF007	09 - MOTOROLA MC68xxx (TM009)		NO CHECKSUM
385	Caterpillar	Caterpillar	Adem III (AT25640 eeprom)	MC68300	TF007	09 - MOTOROLA MC68xxx (TM009)		NO CHECKSUM
648	Caterpillar	Caterpillar	Adem III (HWIII)	MC68300	TF007	09 - MOTOROLA MC68xxx (TM009)		NO CHECKSUM
332	Caterpillar	Caterpillar	Adem IV (561/562)	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		NO CHECKSUM
360	Caterpillar	Caterpillar	Adem IV (563/564 S29CD016G)	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		NO CHECKSUM
408	Caterpillar	Caterpillar	Adem IV (563/564 S29CD032J)	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		NO CHECKSUM
161	Caterpillar	Delphi	Perkins	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		NO CHECKSUM
323	CF Motor	Bosch	MSE3	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E122
409	Chery	Bosch	ME7.9.7	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E118
429	Chery	IAW Marelli	IAW44C	ST10F269	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
576	Chery	Siemens	SIMK31	ST10C167	TF002	05 - SPECIAL ST10 (TM005)		E48
17	Chevrolet / GM Group	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E52
74	Chevrolet / GM Group	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
660	Chevrolet / GM Group	Bosch	EDC16C39	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
519	Chevrolet / GM Group	Bosch	EDC16C42	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
309	Chevrolet / GM Group	Bosch	ME9.1 / ME9.5	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E105
202	Chevrolet / GM Group	Continental	SIM2K	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E111
224	Chevrolet / GM Group / FCA (Fiat/Chrysler Automobiles)	Bosch	ME7.9.9	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E114
465	Chevrolet / GM Group / Opel	Delco	E83	MPC5565	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		E135
14	Chrysler / Jeep	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E52
106	Chrysler / Jeep	Bosch	EDC16+	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
503	Chrysler / Jeep	Bosch	EDC17C49	TC1797	TF003	15 - INFINEON TRICORE BOSCH EDC17 TPROT11 FAL (TM015)		E94
371	Chrysler / Jeep	Motorola	NCG4	MPC5554	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		E139
372	Chrysler / Jeep	Motorola	NCG5	MPC5554	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		E139
193	Cummins engines (generic)	Motorola	CM850	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		NO CHECKSUM
406	Cummins engines (Tractor generic)	Motorola	CM871	MPC565 / MPC566	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		NO CHECKSUM
546	Cummins engines (Truck generic)	Continental	CM2150E	MPC5566	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		NO CHECKSUM
565	Cummins engines (Truck generic)	Motorola	CM870	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		NO CHECKSUM
582	Dacia	Siemens Continental	EMS3130	ST10F273	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E83
819	Daewoo	Delphi	MT60	TC1762 / TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
619	Daewoo	Siemens	D42	ST10C167	TF002	05 - SPECIAL ST10 (TM005)		E48
361	Daewoo / Opel GM Group	Siemens	M300 B10D	ST10C167	TF002	05 - SPECIAL ST10 (TM005)		E48
134	Daf Truck	Bosch	EDC7C-C1	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		NO CHECKSUM

New/ Upg	PLUGIN ID	VEHICLE MANUFACTURER / COSTRUTTORE	ECU BRAND / MARCA ECU	ECU MODEL / MODELLO ECU	CPU (PROCESSOR) / CPU (PROCESSORE)	CPU GROUP / GRUPPO CPU	CPU APPLICATION (SPEC.) / FAMIGLIA CPU (SPEC.)	OBDDI PATCH/ SBLOCCO OBDDI	CHECKSUM MOD./ MOD. CHECKSUM
	506	Daf Truck	Continental	CM2150C	MPC5554	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		NO CHECKSUM
	403	Daf Truck	Continental	CM2150E	MPC5566	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		NO CHECKSUM
	142	Daf Truck	Delphi	DCM1	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E76
	125	Daf Truck	Motorola	CM850	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		NO CHECKSUM
	509	Daf Truck (Paccar Engine)	Delphi	PCX2	MPC5566	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		E138
	742	Daimler Truck (Cummins Engine)	Motorola	CM871	MPC565 / MPC566	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		NO CHECKSUM
	639	Daimler Trucks	Continental	CM2250	MPC5566	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		NO CHECKSUM
	543	Detroit Diesel Trucks	Temic	ACM2	TC1796	TF003	14 - INFINEON TRICORE NO PSW KLINE (TM014)		E132
	627	Detroit Diesel Trucks	Temic	ACM2 - AT25256	TC1796	TF003	14 - INFINEON TRICORE NO PSW KLINE (TM014)		E132
	144	Deutz / Fendt (AGCO Group)	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
	227	Deutz / Fendt (AGCO Group)	Bosch	EDC17CV52	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	572	Deutz / Fendt (AGCO Group)	Bosch	EDC17CV54	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	436	Deutz / Fendt (AGCO Group)	Bosch	EDC17CV56	ST10C167	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	160	Deutz / Fendt (AGCO Group)	Bosch	EDC7U31	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
	80	Dodge	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
	816	Dodge / FCA (Fiat/Chrysler Automobiles)	Bosch	EDC17C79	TC1797	TF003	29 - INFINEON TRICORE BOSCH MEDC17 GPT FCA		E94
	95	Dodge	Motorola	CM848B	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E139
	641	Dodge	Motorola	NCG5	MPC5554	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		E139
New	860	Dodge	Motorola	NCG5	MPC5566	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		E139
	473	Dodge	Siemens	SIM90T	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E110
	566	Dodge (Cummins Engine)	Motorola	CM848E/CM849B	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		NO CHECKSUM
	635	Doosan	Bosch	EDC17CV41	TC1797	TF003	03 - INFINEON TRICORE NO PSW (TM003)		E94
	785	Doosan	Bosch	EDC7U31	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67/E133
	791	Doosan	Bosch	EDC7C1	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E52
	718	Ducati	Continental	M3D	MPC5534	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		E115
	341	Ducati	Continental Siemens VDO	M3C S12X256V	MC9512X5256	TF008	10 - MOTOROLA HC12 (TM010)		E115
	540	Ducati	Continental Siemens VDO	M3C S12X256MAL	MC9512X5256	TF008	10 - MOTOROLA HC12 (TM010)		E115
	756	Ducati	Bosch	ME17.9.21	TC1724	TF003	38 - INFINEON TRICORE BOSCH MED17 GPT DUCATI		E94
	653	Ducati	Melco	HMEI1	MH8106F	TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)		E121
	87	Ducati / MV Augusta	IAW Marelli	SSM	ST10F280	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
	394	Duramax	Bosch	EDC17CP18	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	786	FAW Jiefang	Bosch	EDC7U31	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67/E133
	1	FCA (Fiat/Chrysler Automobiles)	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E52
	70	FCA (Fiat/Chrysler Automobiles)	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
	141	FCA (Fiat/Chrysler Automobiles)	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
	503	FCA (Fiat/Chrysler Automobiles)	Bosch	EDC17C49	TC1797	TF003	15 - INFINEON TRICORE BOSCH EDC17 TPROT11 FAL (TM015)		E94
	655	FCA (Fiat/Chrysler Automobiles)	Bosch	EDC17C69	TC1793	TF003	15 - INFINEON TRICORE BOSCH EDC17 TPROT11 FAL (TM015)		E94
	733	FCA (Fiat/Chrysler Automobiles)	Bosch	EDC17C69	TC1793	TF003	29 - INFINEON TRICORE BOSCH MEDC17 GPT FCA		E94
	363	FCA (Fiat/Chrysler Automobiles)	Bosch	EDC17CP52	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	816	FCA (Fiat/Chrysler Automobiles)	Bosch	EDC17C79	TC1797	TF003	29 - INFINEON TRICORE BOSCH MEDC17 GPT FCA		E94
New	847	FCA (Fiat/Chrysler Automobiles)	Bosch	ME7.9.6	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E91
	24	FCA (Fiat/Chrysler Automobiles)	Bosch	ME7.9.10	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E91
	30	FCA (Fiat/Chrysler Automobiles)	Bosch	MED7.1.1	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E49
	27	FCA (Fiat/Chrysler Automobiles)	Bosch	MED7.6.1	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E91
	26	FCA (Fiat/Chrysler Automobiles)	Bosch	MED7.6.2	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E93
	659	FCA (Fiat/Chrysler Automobiles)	Bosch	ME17.3.0	TC1724	TF003	03 - INFINEON TRICORE NO PSW (TM003)		E94
	642	FCA (Fiat/Chrysler Automobiles)	Bosch	MED17.3.0	TC1724	TF003	15 - INFINEON TRICORE BOSCH EDC17 TPROT11 FAL (TM015)		E94
	150	FCA (Fiat/Chrysler Automobiles)	Bosch	MED17.3.1	TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	643	FCA (Fiat/Chrysler Automobiles)	Bosch	MED17.3.3	TC1793	TF003	15 - INFINEON TRICORE BOSCH EDC17 TPROT11 FAL (TM015)		E94
	823	FCA (Fiat/Chrysler Automobiles)	Bosch	MED17.3.5	TC1793	TF003	29 - INFINEON TRICORE BOSCH MEDC17 GPT FCA		E94
	515	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	4AF.P2	ST10F168	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
	380	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	4CF	ST10F280	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
	381	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	4GF	ST10F296	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
	44	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	4SF / 4DF	ST10F280	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
	63	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	5SF8 / 5SF9	ST10F296	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
	28	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	5SFHWxxx	ST10F280	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
	91	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	6KPB	ST10F296	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E74
	247	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	7GF	MPC5534	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		E101
	645	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	8DF.11	MPC5553	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		E101
	382	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	8F3	MPC5565	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		E101
	245	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	8GF	MPC5553	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		E101
	243	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	8GMF	MPC5565	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		E101
	413	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	8TDF	MPC5553	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		E101
	85	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	MJD 6F3	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E101
	101	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	MJD 6F3	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E101
	349	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	MJD 6F3 HW04W	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E101
	8	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	MJD 6JF	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E101
	303	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	MJD 8DF	MPC5565	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		E101
New	856	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	CFC319 (gearbox)	ST10F280	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E68
	83	FCA (Fiat/Chrysler Automobiles)	Siemens	SID803A 5WS40320	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E92
	38	FCA (Fiat/Chrysler Automobiles) / PSA Group	Visteon	DCU-102	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E92
	366	Fendt (AGCO Group)	Agco	Gearbox	ST10F269	TF002	05 - SPECIAL ST10 (TM005)		NO CHECKSUM
	811	Fendt (AGCO Group)	Agco	Gearbox C167	ST10C167	TF002	05 - SPECIAL ST10 (TM005)		NO CHECKSUM
	335	Ferrari	Bosch	MED9.6.1	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E113
	42	Ferrari / Maserati	Bosch	ME7.3.2	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E89
	823	Ferrari / FCA (Fiat/Chrysler Automobiles)	Bosch	MED17.3.5	TC1793	TF003	29 - INFINEON TRICORE BOSCH MEDC17 GPT FCA		E94
	121	Ford	Bosch	EDC16+	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
	230	Ford	Bosch	EDC17C10	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	698	Ford	Bosch	EDC17C10	TC1797	TF003	28 - INFINEON TRICORE BOSCH MEDC17 GPT FORD		E94
	197	Ford	Bosch	EDC17CP05	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	737	Ford	Bosch	EDC17CP05	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	301	Ford	Bosch	EDC17CP42	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94

New/Upd/New	PLUGIN ID	VEHICLE MANUFACTURER / COSTRUTTORE	ECU BRAND / MARCA ECU	ECU MODEL / MODELLO ECU	CPU (PROCESSOR) / CPU (PROCESSORE)	CPU GROUP / GRUPPO CPU	CPU APPLICATION (SPEC.) / FAMIGLIA CPU (SPEC.)	OBDII PATCH / SBLOCCO OBDII	CHECKSUM MOD. / MOD. CHECKSUM
	863	Ford	Bosch	EDC17C70	TC1793	TF003	20 - INFINEON TRICORE BOSCH MEDC17 TPROT12 FORD		E94
	76	Ford	Bosch	ME9+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E70
	586	Ford	Bosch	MED17.2	TC1767	TF003	20 - INFINEON TRICORE BOSCH MEDC17 TPROT12 FORD		E94
New	831	Ford	Bosch	MED17.2	TC1767	TF003	03 - INFINEON TRICORE NO PSW (TM003)		E94
	618	Ford	Bosch	MED17.2.2	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	200	Ford	Bosch	MED17.8.5	TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	279	Ford	Bosch	MEDG9.8	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E117
	233	Ford	Delphi	DCM	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E62
	302	Ford	Delphi	DCM3.5	MPC5566	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		E100
	343	Ford	FoMoCo	JDS0	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E117
	464	Ford	IAW Marelli	4AFR	ST10F269	TF002	02 - STMICROELECTRONICS ST10 (TM002)		NO CHECKSUM
	393	Ford	IAW Marelli	4CF	ST10F280	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
	663	Ford	Siemens	EMS2205	TC1762 / TC1766	TF003	03 - INFINEON TRICORE NO PSW (TM003)		E83
	145	Ford	Siemens	SID206 5WS40483	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E68
	460	Ford	Siemens	SID901	ST10C167	TF002	05 - SPECIAL ST10 (TM005)		E47
	577	Ford	Siemens	SID902	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E68
	749	Ford	Siemens Continental	EMS2204/2207/2211	TC1738	TF003	16 - INFINEON TRICORE FOMOCO SID208/SID807 (TM016)		E83
	511	Ford	Siemens Continental	SID807EVO	TC1797	TF003	16 - INFINEON TRICORE FOMOCO SID208/SID807 (TM016)	Patch (OBDII Unlock)	E83
	178	Ford	Siemens/Continental	SID807	TC1797	TF003	03 - INFINEON TRICORE NO PSW (TM003)		E83
	20	Ford / Jaguar	Delphi		MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E62
	510	Ford / Land Rover	FoMoCo Continental	SID208	TC1797	TF003	16 - INFINEON TRICORE FOMOCO SID208/SID807 (TM016)	Patch (OBDII Unlock)	E137
	803	Ford / Land Rover	FoMoCo Continental	SID209	TC1797	TF003	16 - INFINEON TRICORE FOMOCO SID208/SID807 (TM016)		E137
	11	Ford / Mazda	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E52
	60	Ford / PSA Group	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
	66	Ford / PSA Group	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
	32	Ford / PSA Group / Volvo	Siemens	SID803 5WS40xxx	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E68
	78	Ford / PSA Group / Volvo	Siemens	SID803A 5WS40xxx	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E68
	238	Ford / Volvo	Bosch	MED17.2	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	82	Ford / Volvo	Siemens	SID206 5WS40xxx	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E68
	31	Ford Truck	Bosch	EDC7C1	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E52
	787	Ford Truck	Bosch	EDC7U31	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67/E133
	504	Ford Truck	Continental	CM2150E	MPC5566	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		NO CHECKSUM
	784	Ford FRD	Bosch	EDC7U31	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67/E133
	461	Freightliner / Mercedes Truck	Temic	DDEC6	TC1796	TF003	14 - INFINEON TRICORE NO PSW KLINE (TM014)		E132
	684	Geely	Delphi	MT80	TC1762 / TC1766	TF003	03 - INFINEON TRICORE NO PSW (TM003)		
	614	Generic Car/LCV	Bosch	EDC17CV42	TC1797	TF003	03 - INFINEON TRICORE NO PSW (TM003)		E94
	595	Generic Tractor	Recon	CM554	MC68300	TF007	09 - MOTOROLA MC68xxx (TM009)		NO CHECKSUM
	615	Generic Truck	Bosch	EDC17CV41	TC1797	TF003	03 - INFINEON TRICORE NO PSW (TM003)		E94/E145
	632	Generic Truck (Cummins Engine)	Continental	CM2250	MPC5566	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		NO CHECKSUM
	7	GM Group / Opel	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E52
	228	GM Group / Opel	Bosch	EDC17C18	TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	153	GM Group / Opel	Bosch	EDC17C19	TC1792	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	688	GM Group / Opel	Bosch	EDC17C59	TC1767	TF003	26 - INFINEON TRICORE BOSCH MEDC17 GPT OPEL		E94
	717	GM Group / Opel	Bosch	EDC17CP47	TC1797	TF003	26 - INFINEON TRICORE BOSCH MEDC17 GPT OPEL		E94
	192	GM Group / Opel	Bosch	ME7.6.4	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E105
	225	GM Group / Opel	Bosch	ME9.6	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E105
	466	GM Group / Opel	Delco	E37	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E135
	520	GM Group / Opel	Delphi	DCM 3.7	SH72544R	TF005	07 - RENESAS SH705x (TM007)		E100
	605	GM Group / Opel	Delphi	DCM 3.7AP	MPC5566	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		E100
	706	GM Group / Opel	Denso	94661024	SH7055	TF005	07 - RENESAS SH705x (TM007)		E121
	253	GM Group / Opel	Denso	1.7 DTI	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
	295	GM Group / Opel	Denso	1.7 DTI SH7059	SH7059	TF005	07 - RENESAS SH705x (TM007)		E121
	10	GM Group / Opel	IAW Marelli	MJD 60F	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E101
	111	GM Group / Opel	IAW Marelli	MJD 602.A6	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E101
	107	GM Group / Opel	IAW Marelli	MJD 602.M1 - MJD 603.S3	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E101
	176	GM Group / Opel	IAW Marelli	MJD 602.M1 - MJD 603.S3	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E101
	333	GM Group / Opel	Siemens	SINTEC 76	ST10C167	TF002	05 - SPECIAL ST10 (TM005)		E48
	309	GM Group / Opel / Chevrolet	Bosch	ME9.1 / ME9.5	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E105
	465	GM Group / Opel / Chevrolet	Delco	E83	MPC5565	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		E135
	458	GM Group / Opel / Chevrolet	Delphi	DCM 3.7	SH72513	TF005	07 - RENESAS SH705x (TM007)		E100
	322	GM Group / Opel / Isuzu	Denso	3.0 V6 DTI	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
	348	GM Group / Opel / Suzuki	IAW Marelli	MJD 602.04	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E101
	84	Great Wall Motor	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
	470	Great Wall Motor	Bosch	EDC17C53	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	439	Great Wall Motor	Bosch	ME7.8.8	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E127
	388	Great Wall Motor	Delphi	DCM 3.7	SH72513	TF005	07 - RENESAS SH705x (TM007)		E100
	487	Hino	Denso	895xx	SH7055	TF005	07 - RENESAS SH705x (TM007)		E121
	347	Hino	Denso	896xx	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
	833	Hino	Denso	175822-799	76F0039AGD	TF010	36 - NEC NBD		E151
	12	Honda	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E52
	731	Honda	Bosch	EDC17C58	TC1793	TF003	35 - INFINEON TRICORE BOSCH MEDC17 GPT HONDA		E94
	805	Honda	Bosch	EDC17CP50	TC1797	TF003	35 - INFINEON TRICORE BOSCH MEDC17 GPT HONDA		E94
	172	Honda	Bosch	EDC17CP06	TC1792	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	213	Honda	Bosch	EDC17CP16	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	497	Honda	Bosch	ME7.9.3	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E21
	810	Honda	Bosch	ME17.9.3	TC1793	TF003	35 - INFINEON TRICORE BOSCH MEDC17 GPT HONDA		E94
	730	Honda	Keihin	37805-Pxx	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
	492	Honda	Keihin	37805-Rxx	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
	617	Honda	Keihin	37820-RAH	SH7055	TF005	07 - RENESAS SH705x (TM007)		E121
	61	Hyundai / Kia	Bosch	EDC16+	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
	72	Hyundai / Kia	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
	164	Hyundai / Kia	Bosch	EDC17C08	TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94

New/ Upg	PLUGIN ID	VEHICLE MANUFACTURER / COSTRUTTORE	ECU BRAND / MARCA ECU	ECU MODEL / MODELLO ECU	CPU (PROCESSOR) / CPU (PROCESSORE)	CPU GROUP / GRUPPO CPU	CPU APPLICATION (SPEC.) / FAMIGLIA CPU (SPEC.)	OBDDI PATCH/ SBLOCCO OBDDI	CHECKSUM MOD./ MOD. CHECKSUM
	608	Hyundai / Kia	Bosch	EDC17C53	TC1767	TF003	19 - INFINEON TRICORE BOSCH MEDC17 TPROT10/11 HYUNDAI/KIA		E94
	682	Hyundai / Kia	Bosch	EDC17C57	TC1793	TF003	19 - INFINEON TRICORE BOSCH MEDC17 TPROT10/11 HYUNDAI/KIA		E94
	127	Hyundai / Kia	Bosch	EDC17CP14	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	549	Hyundai / Kia	Bosch	EDC17CP14	TC1796	TF003	19 - INFINEON TRICORE BOSCH MEDC17 TPROT10/11 HYUNDAI/KIA		E94
	683	Hyundai / Kia	Bosch	M7.9	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E14
	167	Hyundai / Kia	Bosch	M7.9.8	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E106
	339	Hyundai / Kia	Bosch	ME17.9.11	TC1762 / TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	597	Hyundai / Kia	Bosch	ME7.9.7	ST10F275	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E118
	496	Hyundai / Kia	Bosch	MED17.9.8	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	550	Hyundai / Kia	Bosch	MED17.9.8/MEDG17.9.8	TC1767	TF003	19 - INFINEON TRICORE BOSCH MEDC17 TPROT10/11 HYUNDAI/KIA		E94
	416	Hyundai / Kia	Bosch	MEG17.9.11	TC1762 / TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	693	Hyundai / Kia	Bosch	MEG17.9.2	TC1767	TF003	19 - INFINEON TRICORE BOSCH MEDC17 TPROT10/11 HYUNDAI/KIA		E94
New	867	Hyundai / Kia	Bosch	EDC17C53	TC1767	TF003	41 - INFINEON TRICORE BOSCH MEDC17 GPT HYUNDAI/KIA		E94
New	858	Hyundai / Kia	Bosch	EDC17CP62	TC1793	TF003	19 - INFINEON TRICORE BOSCH MEDC17 TPROT10/11 HYUNDAI/KIA		E94
	194	Hyundai / Kia	Continental	SIM2K	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E111
	387	Hyundai / Kia	Delphi	DCM 3.7	SH72513	TF005	07 - RENESAS SH705x (TM007)		E100
	317	Hyundai / Kia	Kefico	EH8	MH8305H	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		NO CHECKSUM
	351	Hyundai / Kia	Kefico	KTS3	MH8X02F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		E121
	575	Hyundai / Kia	Mitsubishi	39106-3945x	MH82XXF	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		NO CHECKSUM
	367	Hyundai / Kia	Siemens	SIM2K-47 5WY4Cxxx #L	ST10C167	TF002	05 - SPECIAL ST10 (TM005)		E48
	368	Hyundai / Kia	Siemens	SIM2K-47 5WY4Cxxx #R	ST10C167	TF002	05 - SPECIAL ST10 (TM005)		E48
	352	Hyundai / Kia	Siemens	SIMK43 5WY1xxxx	ST10C167	TF002	05 - SPECIAL ST10 (TM005)		E48
	353	Hyundai / Kia	Siemens	SIMK43 5WY44xxx #L	ST10C167	TF002	05 - SPECIAL ST10 (TM005)		E48
	354	Hyundai / Kia	Siemens	SIMK43 5WY44xxx #R	ST10C167	TF002	05 - SPECIAL ST10 (TM005)		E48
	521	Hyundai / Kia	Siemens Continental	SIM2K	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E111
	169	Hyundai / Kia (Cummins)	Motorola	CM850	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		NO CHECKSUM
	112	Hyundai / Kia / Ssangyong	Delphi	DCM3.2	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E81
	623	Hyundai Trago	Delphi	ETC3	MPC5566	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		E138
	621	International Truck	Bosch	EDC7UC31	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
	804	International Truck	Siemens	SID904	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		NO CHECKSUM
	400	International Truck (Cummins)	Motorola	CM870	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		NO CHECKSUM
	401	International Truck (Cummins)	Motorola	CM871 / CM876	MPC565 / MPC566	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		NO CHECKSUM
	745	Isuzu	Bosch	EDC17CV41	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	412	Isuzu	Denso	25841077	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
New	852	Isuzu	Denso	275800-8755	SH7059	TF005	07 - RENESAS SH705x (TM007)		E121
	430	Isuzu	Transtron	4Jxx	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
	490	Isuzu	Transtron		SH72544R	TF005	07 - RENESAS SH705x (TM007)		E121
	703	Isuzu	Transtron		SH7059	TF005	07 - RENESAS SH705x (TM007)		E121
	313	Isuzu	Transtron		SH7055	TF005	07 - RENESAS SH705x (TM007)		E121
	79	Isuzu / Chevrolet	Delphi		MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E82
	322	Isuzu / GM Group / Opel	Denso	3.0 V6 DTI	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
	579	Isuzu Giga	Denso	895xx	SH7055	TF005	07 - RENESAS SH705x (TM007)		E121
	130	Iveco	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E52
	140	Iveco	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
	206	Iveco	Bosch	EDC17	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	432	Iveco	Bosch	EDC17C49	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	633	Iveco	Bosch	EDC17CV41	TC1797	TF003	03 - INFINEON TRICORE NO PSW (TM003)		E145
	568	Iveco	IAW Marelli	SSF4	ST10F296	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
	129	Iveco / New Holland	Bosch	EDC7C1-C2	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E63
	137	Iveco / New Holland	Bosch	EDC7U31	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67/E133
	346	Jaguar	Denso	MB079700	SH7055	TF005	07 - RENESAS SH705x (TM007)		NO CHECKSUM
	422	Jaguar	Denso	MB279700-9xxx	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
	105	Jaguar	Siemens	SID201 - SID204 5WS40xxx	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E68
	845	Jaguar / Land Rover	Bosch	EDC17CP55	TC1793	TF003	25 - INFINEON TRICORE BOSCH MEDC17 GPT JAGUAR (TM025)		E94
New	864	Jaguar / Land Rover	Bosch	EDC17CP55	TC1793	TF003	20 - INFINEON TRICORE BOSCH MEDC17 TPROT12 FORD		E94
	685	Jaguar / Land Rover	Bosch	MED17.8.31	TC1797	TF003	25 - INFINEON TRICORE BOSCH MEDC17 GPT JAGUAR (TM025)		E94
New	828	Jaguar / Land Rover	Bosch	MED17.9	TC1793	TF003	25 - INFINEON TRICORE BOSCH MEDC17 GPT JAGUAR (TM025)		E94
	827	Jaguar / Land Rover	Bosch	MED17.9.7	TC1767	TF003	25 - INFINEON TRICORE BOSCH MEDC17 GPT JAGUAR (TM025)		E94
	498	Jaguar / Land Rover	Denso	P5.05C	SH7059	TF005	07 - RENESAS SH705x (TM007)		E121
	593	JCB	Continental	CM2250	MPC5566	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		NO CHECKSUM
	560	JCB	Delphi	DCM TIER III	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
	701	JCB	Delphi	DCM3.3	SH72544R	TF005	07 - RENESAS SH705x (TM007)		E100
	402	JCB / Massey Ferguson	Bosch	EDC17CV54	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	191	JCB Fastrack	Motorola	CM850	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		NO CHECKSUM
	807	JMC	Bosch	EDC17C55	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	598	Jeep	Bosch	EDC17C79	TC1797	TF003	15 - INFINEON TRICORE BOSCH EDC17 TPROT11 FAL (TM015)		E94
	256	Jeep	Bosch	EDC17CP27	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	77	Jeep / Mitsubishi	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
	190	John Deere	Motorola	CM850	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		NO CHECKSUM
	462	John Deere	Phoenix	L11	ST10F168	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E104
	123	John Deere	Phoenix	L14	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E104
	236	John Deere	Phoenix	L16	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E104
	463	John Deere	Phoenix	L4	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E104
	508	John Deere	Phoenix	L9/L11	ST10F269	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E104
	457	John Deere	Siemens	IUC2	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		NO CHECKSUM
	522	Kawasaki	Denso	21775-0046	SH7054	TF005	07 - RENESAS SH705x (TM007)		E121
	818	Kawasaki	Denso	21175-0077	SH7054	TF005	07 - RENESAS SH705x (TM007)		E121
	532	Kawasaki	Denso	21775-0097	SH7054	TF005	07 - RENESAS SH705x (TM007)		E121
	817	Kawasaki	Denso	21175-0187	SH7054	TF005	07 - RENESAS SH705x (TM007)		E121
	525	Kawasaki	Denso	21175-0220	M32R196	TF009	17 - RENESAS M32R (TM017)		E121
New	854	Kawasaki	Denso	21175-027X/03XX		TF009	17 - RENESAS M32R (TM017)		E121
	687	Kawasaki	Denso	21175-03XX	M32R196	TF009	17 - RENESAS M32R (TM017)		E121

New/ Upg	PLUGIN ID	VEHICLE MANUFACTURER / COSTRUTTORE	ECU BRAND / MARCA ECU	ECU MODEL / MODELLO ECU	CPU (PROCESSOR) / CPU (PROCESSORE)	CPU GROUP / GRUPPO CPU	CPU APPLICATION (SPEC.) / FAMIGLIA CPU (SPEC.)	OBDDI PATCH/ SBLOCCO OBDDI	CHECKSUM MOD./ MOD. CHECKSUM
	620	Kawasaki	Denso	21775-07XX	SH7054	TF005	07 - RENESAS SH705x (TM007)		E121
	652	Kawasaki	Denso	21175-08XX	M32R196	TF009	17 - RENESAS M32R (TM017)		E121
	561	Kawasaki	Denso	21775-109X	SH7054	TF005	07 - RENESAS SH705x (TM007)		E121
	530	Kawasaki	Melco	21175-3732	MH7203	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		NO CHECKSUM
	455	Kawasaki	Melco	ULTRA 300x	MH8106F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		E121
	637	Kawasaki	Mitsubishi	21175-033X	MH8102F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx		E121
	625	Kawasaki	Mitsubishi	21175-076X	MH8102F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx		E121
	285	Kawasaki	Mitsubishi	JetSki Ultra 250	MH82XXF	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		E121
	300	Kawasaki	Mitsubishi	2ZR1200	MH8305F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		E121
	484	Kawasaki	Mitsubishi	2X10R	MH82XXF	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx		E121
	488	Kawasaki	Mitsubishi	2X10R MY07	MH82XXF	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx		E121
	744	Kenworth Truck (Cummins Engine)	Motorola	CM871	MPC565 / MPC566	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		NO CHECKSUM
	541	Khodro/Saipa	Continental	SIM2K-34 5WY5Kxxx	ST10C167	TF002	05 - SPECIAL ST10 (TM005)		E48
	379	King Long	Continental	CM2150E	MPC5566	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		NO CHECKSUM
	438	Komatsu	Motorola	CM850	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		NO CHECKSUM
	418	Ktm	Bosch	M17.8.7	TC1762 / TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	773	Kubota	Bosch	EDC17C55	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	584	Kubota	Denso	275700-1201	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
	578	Kubota	Denso	275800-7221	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
	376	Lada / UAZ	Bosch	M7.9.7	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E118
	428	Lada / UAZ	Bosch	ME17.9.7	TC1762 / TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	469	Lamborghini	Campi		MC68300	TF007	09 - MOTOROLA MC68xxx (TM009)		NO CHECKSUM
	120	Land Rover	Bosch	EDC16+	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
	177	Land Rover	Bosch	EDC17CP11	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	235	Land Rover	Bosch	EDC17CP42	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	483	Land Rover	Denso	MB279700-94xx	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
	98	Land Rover	Siemens	SID201 - SID204 5WS40xxx	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E68
	115	Land Rover	Siemens	SID203 5WS40371	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E68
	384	Land Rover	Siemens	SID204 5WS40xxx	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E68
	37	Land Rover	Visteon	DCU-106	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E92
	510	Land Rover / Ford	FoMoCo Continental	SID208	TC1797	TF003	16 - INFINEON TRICORE FOMOCO SID208/SID807 (TM016)		E137
	498	Land Rover / Jaguar	Denso	P5.05C	SH7059	TF005	07 - RENESAS SH705x (TM007)		E121
	310	LDV	Bosch	EDC16+ C39	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
	567	Lindner Perkins	Bosch	EDC17C49	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	287	Lotus	Efi		MC68300	TF007	09 - MOTOROLA MC68xxx (TM009)		NO CHECKSUM
	306	Lotus	Efi		MC68300	TF007	09 - MOTOROLA MC68xxx (TM009)		NO CHECKSUM
	437	Lotus	Efi	T4E	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E129
	507	Lotus	Efi	T6E	MPC5534	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		E129
	447	LTI	Bosch	EDC16+ C39	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
	453	Mack	Bosch	EDC7U/U1	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E130
	21	Mahindra	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E52
	699	Mahindra	Bosch	EDC16 C39	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
	558	Mahindra	Bosch	EDC17C53	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	495	Mahindra	Bosch	EDC17C55	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	538	Man Latin America / Volkswagen Trucks	Continental	CM2150E	MPC5566	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		NO CHECKSUM
	135	Man Truck	Bosch	EDC7C3	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E66
	139	Man Truck	Bosch	EDC7C32	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
	596	Maserati	Bosch	EDC17C79	TC1797	TF003	15 - INFINEON TRICORE BOSCH EDC17 TPROT11_FAL (TM015)		E94
	226	Maserati	Bosch	ME911	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E113
	711	Maserati	Bosch	MED17.3.4	TC1797	TF003	29 - INFINEON TRICORE BOSCH MEDC17 GPT FCA		E94
	402	Massey Ferguson / JCB	Bosch	EDC17CV54	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	270	Massey Ferguson / McCormick / Caterpillar	Perkins	Caterpillar Tier2	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		NO CHECKSUM
	651	Maz Trucks	Bosch	EDC7UC31	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
	395	Mazda	Denso	N311	SH7055	TF005	07 - RENESAS SH705x (TM007)		E121
	263	Mazda	Denso	R2AX	SH7059	TF005	07 - RENESAS SH705x (TM007)		E121
	278	Mazda	Denso	RF7K	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
	476	Mazda	Denso	L3T4	SH7055	TF005	07 - RENESAS SH705x (TM007)		E121
	518	Mazda	Denso	L3TA	SH7055	TF005	07 - RENESAS SH705x (TM007)		E121
	321	Mazda	Denso	L831	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
	327	Mazda	Denso	R2AA	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
	277	Mazda	Denso	RF8G	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
	344	Mazda	Denso	Z177	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
	454	Mazda	Denso	ZY69	SH7059	TF005	07 - RENESAS SH705x (TM007)		E121
	517	Mazda	Mitsubishi	E6T540xxxx	MH8105F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		E121
	603	Mazda	Mitsubishi	E6T58xxx	MH8106F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		E121
	373	Mazda	Mitsubishi	E6T5x	MH8105F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		E121
	475	Mazda	Mitsubishi	FPV1EA	MH7203	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		NO CHECKSUM
	345	Mazda	Mitsubishi	L3B1	MH8305F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		NO CHECKSUM
	708	McLaren	Bosch	MED17.8.3	TC1797	TF003	30 - INFINEON TRICORE BOSCH MEDC17 GPT McLAREN		E94
	4	Mercedes	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
	7	Mercedes	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E52
	97	Mercedes	Bosch	EDC16+	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
	114	Mercedes	Bosch	EDC16+	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
	222	Mercedes	Bosch	EDC17C01	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	231	Mercedes	Bosch	EDC17C43	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	700	Mercedes	Bosch	EDC17C57	TC1793	TF003	27 - INFINEON TRICORE BOSCH MEDC17 GPT MERCEDES		E94
	710	Mercedes	Bosch	EDC17C66	TC1793	TF003	27 - INFINEON TRICORE BOSCH MEDC17 GPT MERCEDES		E94
	157	Mercedes	Bosch	EDC17CP01	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	155	Mercedes	Bosch	EDC17CP10	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	182	Mercedes	Bosch	EDC17CP10	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	273	Mercedes	Bosch	EDC17CP10	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	365	Mercedes	Bosch	EDC17CP46	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94

New/Upg	PLUGIN ID	VEHICLE MANUFACTURER / COSTRUTTORE	ECU BRAND / MARCA ECU	ECU MODEL / MODELLO ECU	CPU (PROCESSOR) / CPU (PROCESSORE)	CPU GROUP / GRUPPO CPU	CPU APPLICATION (SPEC.) / FAMIGLIA CPU (SPEC.)	OBDDI PATCH / SBLOCCO OBDDI	CHECKSUM MOD. / MOD. CHECKSUM
	691	Mercedes	Bosch	EDC17CP46	TC1797	TF003	27 - INFINEON TRICORE BOSCH MEDC17 GPT MERCEDES		E94
	622	Mercedes	Bosch	ME2.8	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E16
	102	Mercedes	Bosch	ME9.7	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E79
	204	Mercedes	Bosch	ME9.7	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E79
	692	Mercedes	Bosch	MED17.7.2	TC1797	TF003	27 - INFINEON TRICORE BOSCH MEDC17 GPT MERCEDES		E94
	736	Mercedes	Bosch	MED17.7.1/MED17.7.3	TC1797	TF003	27 - INFINEON TRICORE BOSCH MEDC17 GPT MERCEDES		E94
	740	Mercedes	Bosch	MED17.7.3.1	TC1797	TF003	27 - INFINEON TRICORE BOSCH MEDC17 GPT MERCEDES		E94
	249	Mercedes	Bosch	MED17.1	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
New	714	Mercedes	Bosch	MED17.7.5	TC1793	TF003	27 - INFINEON TRICORE BOSCH MEDC17 GPT MERCEDES		E94
	514	Mercedes	Bosch	MED17.7.8	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	248	Mercedes	Delphi	CRD2.10	MPC5566	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		E100
	808	Mercedes	Delphi	CRD3.40	TC1797	TF003	03 - INFINEON TRICORE NO PSW (TM003)		E83
	809	Mercedes	Delphi	CRD3.50	TC1797	TF003	03 - INFINEON TRICORE NO PSW (TM003)		E83
	119	Mercedes	Delphi	DCM3.2	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E81
	580	Mercedes	Siemens	EGS52	ST10C167	TF002	05 - SPECIAL ST10 (TM005)		E146
	581	Mercedes	Siemens	EGS53	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E146
	175	Mercedes	Siemens	SIM 266	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E124
	500	Mercedes	Siemens	SIM 266 (ex flash S29CD032)	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E124
	542	Mercedes Truck	Continental	HDEP	TC1796	TF003	14 - INFINEON TRICORE NO PSW KLINE (TM014)		E132
	628	Mercedes Truck	Continental	HDEP MCM2.1	TC1797	TF003	14 - INFINEON TRICORE NO PSW KLINE (TM014)		E132
	461	Mercedes Truck / Freightliner	Temic	DDEEC6	TC1796	TF003	14 - INFINEON TRICORE NO PSW KLINE (TM014)		E132
	189	Mercury Marine	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
	33	Mercury Marine	Motorola	ECM04xx	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E119
	442	Mercury Marine	Motorola	ECM0501	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E119
	90	Mercury Marine	Motorola	ECM070xx	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E119
	132	Mercury Marine	Motorola	ECM555	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E119
	36	Mercury Marine	Motorola	PCM0308	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E119
	35	Mercury Marine	Motorola	PCM0702	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E119
	441	Mercury Marine	Motorola	PCM08xx	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E119
	34	Mercury Marine	Motorola	PCMBE0101	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E119
	419	MG	Bosch	ME9.9.71	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E118
	152	Mini	Bosch	MED172/MEV172 (Irom)	TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	237	Mini	Bosch	MEV17.2.2	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	208	Mini	Bosch	MEVD17.2.2	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	719	Mini	Bosch	MEVD17.2.3	TC1793	TF003	22 - INFINEON TRICORE BOSCH EDC17 GPT BMW		E94
	43	Mitsubishi	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E52
	640	Mitsubishi	Bosch	EDC17C49	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	170	Mitsubishi	Bosch	EDC17CP15 (xrom)	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	588	Mitsubishi	Bosch	EDC17CP52	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	573	Mitsubishi	Bosch	ME7.7.1	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E144
	265	Mitsubishi	Denso	(4D56 engine)	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
	601	Mitsubishi	Denso	6M60	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
	629	Mitsubishi	Denso	6M60	SH7055	TF005	07 - RENESAS SH705x (TM007)		E121
	283	Mitsubishi	Denso	EVOX	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
	319	Mitsubishi	Denso	RA6	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
	417	Mitsubishi	Denso	RA6 4D56	SH7059	TF005	07 - RENESAS SH705x (TM007)		E121
	324	Mitsubishi	Denso	RA6 4N13	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
	232	Mitsubishi	IAW Marelli	4AM	ST10F269	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
	337	Mitsubishi	IAW Marelli	4CM	ST10F280	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
	444	Mitsubishi	IAW Marelli	4DM	ST10F280	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
	423	Mitsubishi	IAW Marelli	4GM	ST10F296	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
	589	Mitsubishi	IAW Marelli	4GT	ST10F296	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
	548	Mitsubishi	IAW Marelli	IAW4DM CR47	ST10F280	TF002	02 - STMICROELECTRONICS ST10 (TM002)		NO CHECKSUM
	350	Mitsubishi	Melco	G1Tx	MH8X02F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		E121
	318	Mitsubishi	Mitsubishi	3.2 D	MH7203	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		E121
	570	Mitsubishi	Mitsubishi	E2711xxx	MH8102F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		E121
	609	Mitsubishi	Mitsubishi	E2779xxx	MH8306F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		NO CHECKSUM
	449	Mitsubishi	Mitsubishi	E277xxx MH7203	MH7203	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		NO CHECKSUM
	479	Mitsubishi	Mitsubishi	E67310xx	MH8305F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		NO CHECKSUM
	493	Mitsubishi	Mitsubishi	E67310xx	MH8305F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		E121
	585	Mitsubishi	Mitsubishi	E6736xxx	MH8102F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		E121
	474	Mitsubishi	Mitsubishi	E6738xxx	MH8102F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		NO CHECKSUM
	482	Mitsubishi	Mitsubishi	E6741xxx	MH8102F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		E121
	602	Mitsubishi	Mitsubishi	E6744xxx	MH8304F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		E121
	410	Mitsubishi	Mitsubishi	E6747xxx	MH8102F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		NO CHECKSUM
	391	Mitsubishi	Mitsubishi	E6749xxx	MH8304F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		E121
	583	Mitsubishi	Mitsubishi	E6774xxx	MH8102F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		E121
	426	Mitsubishi	Mitsubishi	E6776xxx	MH8106F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		E121
	328	Mitsubishi	Mitsubishi	E677x	MH8106F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		E121
	329	Mitsubishi (Colt 1.5 asp.)	Mitsubishi	MH7x/MH8x	MH8102F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		E121
	255	Mitsubishi (Colt 1.5 turbo)	Mitsubishi	MH7x/MH8x	MH8203F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		E121
	261	Mitsubishi (Lancer EVO IX)	Mitsubishi	MH7x/MH8x	MH8305F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		NO CHECKSUM
	259	Mitsubishi (Lancer EVO VII)	Mitsubishi	MH7x/MH8x	MH7202F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		NO CHECKSUM
	260	Mitsubishi (Lancer EVO VII/VIII)	Mitsubishi	MH7x/MH8x	MH7202F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		NO CHECKSUM
	297	Mitsubishi (Pajero 3.2 DI-D)	Mitsubishi	MH7x/MH8x	MH8305F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		E121
	99	Mitsubishi / Smart	Bosch	EDC16+	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
	547	Moto Guzzi	IAW Marelli	IAW75M	ST10F296	TF002	02 - STMICROELECTRONICS ST10 (TM002)		NO CHECKSUM
	217	MV Agusta	IAW Marelli	7BM	ST10F296	TF002	02 - STMICROELECTRONICS ST10 (TM002)		NO CHECKSUM
	143	New Holland	Bosch	EDC16+ C39/UC40	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
	467	New Holland / Case	Bosch	EDC17C49	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94/E145
	129	New Holland / Iveco	Bosch	EDC7C1-C2	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E63
	137	New Holland / Iveco	Bosch	EDC7U31	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67/E133

New/ Upg	PLUGIN ID	VEHICLE MANUFACTURER / COSTRUTTORE	ECU BRAND / MARCA ECU	ECU MODEL / MODELLO ECU	CPU (PROCESSOR) / CPU (PROCESSORE)	CPU GROUP / GRUPPO CPU	CPU APPLICATION (SPEC.) / FAMIGLIA CPU (SPEC.)	OBDDI PATCH/ SBLOCCO OBDDI	CHECKSUM MOD./ MOD. CHECKSUM
	478	Nissan	Bosch	EDC16CP42	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
	657	Nissan	Bosch	EDC17C45	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	724	Nissan	Bosch	EDC17C84	TC1782	TF003	32 - INFINEON TRICORE BOSCH MEDC17 GPT NISSAN		E94
	294	Nissan	Denso	1H	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
	264	Nissan	Denso	D3	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
	314	Nissan	Denso	HP	SH7059	TF005	07 - RENESAS SH705x (TM007)		E121
	315	Nissan	Denso	HWII	SH7055	TF005	07 - RENESAS SH705x (TM007)		E121
	647	Nissan	Hitachi	23710-5Y222	SH7055	TF005	07 - RENESAS SH705x (TM007)		E121
	445	Nissan	Hitachi	A56-B7x	SH7055	TF005	07 - RENESAS SH705x (TM007)		E121
	450	Nissan	Hitachi	A56-C1x	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
	661	Nissan	Hitachi	A56-U45	SH7055	TF005	07 - RENESAS SH705x (TM007)		E121
	481	Nissan	Hitachi	BED301-000	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
	448	Nissan	Hitachi	DEA030-2xx	SH7059	TF005	07 - RENESAS SH705x (TM007)		E121
	296	Nissan	Hitachi	HPNGV	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
	396	Nissan	Hitachi	HPNGV SH7059	SH7059	TF005	07 - RENESAS SH705x (TM007)		E121
	298	Nissan	Hitachi	HW 1	SH7055	TF005	07 - RENESAS SH705x (TM007)		E121
	299	Nissan	Hitachi	HW 4	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
	502	Nissan	Hitachi	MEC-100-xxx	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
	414	Nissan	Hitachi	MEC-107	SH7059	TF005	07 - RENESAS SH705x (TM007)		E121
	494	Nissan	Hitachi	MEC-23-xxx	SH7055	TF005	07 - RENESAS SH705x (TM007)		E121
	451	Nissan	Hitachi	MEC-30-07x	SH7055	TF005	07 - RENESAS SH705x (TM007)		E121
	600	Nissan	Hitachi	MEC-35	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
	650	Nissan	Hitachi	MEC-37-3xx	SH7054	TF005	07 - RENESAS SH705x (TM007)		E121
	680	Nissan	Hitachi	MEC-37-900	SH7055	TF005	07 - RENESAS SH705x (TM007)		E121
	694	Nissan	Hitachi	MEC-38-310	SH7055	TF005	07 - RENESAS SH705x (TM007)		E121
	415	Nissan	Hitachi	MEC-73-xxx	SH7059	TF005	07 - RENESAS SH705x (TM007)		E121
	606	Nissan	Hitachi	MEC-78-xxx	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
	501	Nissan	Hitachi	MEC-90-xxx	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
	587	Nissan	Hitachi	MEC-940-xxx	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
	486	Nissan Truck (Cummins engine)	Motorola	CM850	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		NO CHECKSUM
	431	Peterbilt Truck (Cummins engine)	Motorola	CM870	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		NO CHECKSUM
	377	Piaggio	Bosch	EDC17C08	TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	307	Polaris	Bosch	M17.8.7	TC1762	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	673	Polaris	Bosch	M17.9.74	TC1762 / TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	56	Polaris	Bosch	M7.4.4	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E71
	57	Polaris	Bosch	ME7.4.4	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E71
	282	Polaris	Bosch	ME7.9.7	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E71
	240	Porsche	Bosch	ME7.2	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E27
	242	Porsche	Bosch	ME7.8	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E27
	41	Porsche	Bosch	ME7.8.1	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E27
	40	Porsche	Bosch	ME7.8.2	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E87
	159	Porsche	Bosch	ME7.8.2 min	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E87
	793	Porsche	Bosch	MED17.1.11	TC1797	TF003	23 - INFINEON TRICORE BOSCH MEDC17 GPT VAG		E94
	39	Porsche	Siemens/Continental	VDO SDI3/SDI4	TC1796	TF003	03 - INFINEON TRICORE NO PSW (TM003)		E96
	272	Porsche	Siemens/Continental	VDO SDI6	TC1796	TF003	11 - INFINEON TRICORE SIEMENS SDI6 PORSCHE (TM011)		E96
	108	Porsche / VAG (VW Group)	Bosch	MED9.1 FSI - MED9.1.1 FSI	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E58/E85/E123
	534	Proton	Siemens VDO	PW5XX	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E140
	535	Proton	Siemens VDO	PW8XX	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E140
	5	PSA Group	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E52
	118	PSA Group	Bosch	EDC16+	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
	728	PSA Group	Bosch	EDC17C60	TC1793	TF003	34 - INFINEON TRICORE BOSCH MEDC17 GPT PSA		E94
	198	PSA Group	Bosch	EDC17CP10	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	219	PSA Group	Bosch	EDC17C10	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	312	PSA Group	Bosch	EDC17CP42	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	551	PSA Group	Bosch	M7.4.4	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E32
	397	PSA Group	Bosch	ME7.4.4	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E32
	25	PSA Group	Bosch	ME7.4.5	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E88
	569	PSA Group	Bosch	ME7.4.6	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E32
	47	PSA Group	Bosch	ME7.4.9	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E88
	729	PSA Group	Bosch	MED17.4.4	TC1793	TF003	34 - INFINEON TRICORE BOSCH MEDC17 GPT PSA		E94
	196	PSA Group	Bosch	MED17.4/MEV17.4	TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	305	PSA Group	Bosch	MED17.4/MEV17.4 (Irom)	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	209	PSA Group	Bosch	MED17.4/MEV17.4 (xrom)	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	286	PSA Group	Bosch	MEV17.4.2	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	216	PSA Group	Bosch	MEV17.4.2	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	741	PSA Group	Bosch	MEV17.4.4	TC1793	TF003	34 - INFINEON TRICORE BOSCH MEDC17 GPT PSA		E94
	257	PSA Group	Delphi	DCM3.4	SH7058	TF005	07 - RENESAS SH705x (TM007)		E100
	362	PSA Group	Delphi	DCM3.4	SH7059	TF005	07 - RENESAS SH705x (TM007)		E100
	244	PSA Group	Delphi	DCM3.5	MPC5566	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		E100
	55	PSA Group	Delphi	DDCR	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E100
	45	PSA Group	IAW Marelli	6LP.49	ST10F280	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E74
	46	PSA Group	IAW Marelli	6LPC.102	ST10F280	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E74
	599	PSA Group	Siemens	S2000	ST10C167	TF002	05 - SPECIAL ST10 (TM005)		E60
	104	PSA Group	Siemens	SID201 5WS40xxx	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E68
	443	PSA Group	Siemens	SID801	ST10C167	TF002	05 - SPECIAL ST10 (TM005)		E26
	320	PSA Group	Siemens/Continental	SID807 (Irom)	TC1797	TF003	03 - INFINEON TRICORE NO PSW (TM003)		E83
	359	PSA Group	Siemens/Continental	SID807 (xrom)	TC1796	TF003	03 - INFINEON TRICORE NO PSW (TM003)		E83
	122	PSA Group	Valeo Johnson	J34P	ST10F273	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E103
	211	PSA Group	Valeo Johnson	J34P	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E103
	491	PSA Group	Valeo Johnson	J34P HW II	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E103
	6	Renault Group	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E52
	133	Renault Group	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E52

New/ Upg	PLUGIN ID	VEHICLE MANUFACTURER / COSTRUTTORE	ECU BRAND / MARCA ECU	ECU MODEL / MODELLO ECU	CPU (PROCESSOR) / CPU (PROCESSORE)	CPU GROUP / GRUPPO CPU	CPU APPLICATION (SPEC.) / FAMIGLIA CPU (SPEC.)	OBDDI PATCH/ SBLOCCO OBDDI	CHECKSUM MOD./ MOD. CHECKSUM
	29	Renault Group	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
	62	Renault Group	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
	69	Renault Group	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
	223	Renault Group	Bosch	EDC16C36	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
	234	Renault Group	Bosch	EDC16CP33	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
	201	Renault Group	Bosch	EDC17C11	TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	181	Renault Group	Bosch	EDC17CP19	TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	456	Renault Group	Bosch	EDC17CP58	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	790	Renault Group	Bosch	EDC17C84	TC1782	TF003	31 - INFINEON TRICORE BOSCH MEDC17 GPT RENAULT		E94
	720	Renault Group	Bosch	ME7.4.6	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E32
	709	Renault Group	Bosch	MED17.9.20	TC1782	TF003	31 - INFINEON TRICORE BOSCH MEDC17 GPT RENAULT		E94
	258	Renault Group	Delphi	DCM3.4	SH7059	TF005	07 - RENESAS SH705x (TM007)		E100
	529	Renault Group	Hitachi	A56-xxx	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
	799	Renault Group	Hitachi	EW20-0xx	SH7055	TF005	07 - RENESAS SH705x (TM007)		E121
	531	Renault Group	Hitachi	MEC121-xxx	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
	571	Renault Group	Hitachi	MEC800	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
	768	Renault Group	Hitachi	MEC099-xxx	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
	88	Renault Group	Sagem	S2000RPM	ST10C167	TF002	05 - SPECIAL ST10 (TM005)		E60
	250	Renault Group	Sagem	S3000	SH7055	TF005	07 - RENESAS SH705x (TM007)		E73
	210	Renault Group	Siemens	EMS3110	TC1766	TF003	03 - INFINEON TRICORE NO PSW (TM003)		E83
	844	Renault Group	Siemens	EMS3134	ST10C167	TF002	05 - SPECIAL ST10 (TM005)		E28
	81	Renault Group	Siemens	SID301	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E83
	205	Renault Group	Siemens	SID305	TC1766	TF003	03 - INFINEON TRICORE NO PSW (TM003)		E83
	252	Renault Group	Siemens	SIM32	SH7055	TF005	07 - RENESAS SH705x (TM007)		E73
	336	Renault Group	Siemens	SIRIUS 32	ST10C167	TF002	05 - SPECIAL ST10 (TM005)		E25
	471	Renault Group	Siemens	SIRIUS 34	ST10C167	TF002	05 - SPECIAL ST10 (TM005)		E28
	280	Renault Group	Valeo	S3000	SH7058	TF005	07 - RENESAS SH705x (TM007)		E73
	251	Renault Group	Valeo	V40	SH7058	TF005	07 - RENESAS SH705x (TM007)		E73
	398	Renault Group / Nissan	Bosch	EDC17C42	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	292	Renault Group / Samsung	Hitachi	DA A56-Y8x	SH7055	TF005	07 - RENESAS SH705x (TM007)		E121
	138	Renault Truck / Volvo Truck	TRW	EMS2	MPC565 / MPC566	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E80
	330	Rotax	Siemens VDO	MSE 3.7	ST10F269	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E126
	411	Rotax	Siemens VDO	MSE 3.7 R/H3	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E126
	180	Rotax (Sea Doo Acqua Scooter)	Bosch	ME17.8.5	TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	654	Same	Bosch	EDC17C53	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	590	Scania Truck	Continental	EMS 57	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E64
	594	Scania Truck	Continental	EMS 58	MPC5566	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		E64
	131	Scania Truck	Motorola	EDCS6	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E64
	738	Sinotruck	Bosch	EDC17CV44	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	23	Smart	Bosch	ME7.7.0	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E90
	480	Smart	Mitsubishi	G27601x Gearbox	MH8102F	TF006	08 - MITSUBISHI MH7xxx/MH8xxx		E121
	459	Ssangyong	Delphi	DCM 3.7	SH72513	TF005	07 - RENESAS SH705x (TM007)		E100
	524	Ssangyong	Delphi	DCM 3.7	SH72544R	TF005	07 - RENESAS SH705x (TM007)		E100
	22	Ssangyong	Delphi		MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E65
	564	Subaru	Denso	112200-8481	SH7055	TF005	07 - RENESAS SH705x (TM007)		E121
	630	Subaru	Denso	112300-0430	SH7055	TF005	07 - RENESAS SH705x (TM007)		E121
	281	Subaru	Denso	CJ	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
	375	Subaru	Denso	DM	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
	276	Subaru	Denso	DT	SH7059	TF005	07 - RENESAS SH705x (TM007)		E121
	275	Subaru	Denso	KS	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
	644	Subaru	Hitachi	DEF002-XXX	SH7059	TF005	07 - RENESAS SH705x (TM007)		E121
	16	Suzuki	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E52
	212	Suzuki	Bosch	EDC16+	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E52
	446	Suzuki	Bosch	EDC16+ C39	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
	340	Suzuki	Bosch	ME17.8.XX	TC1767 / TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	434	Suzuki	Bosch	ME17.8.XX	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	370	Suzuki	Denso	057L1	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
	331	Suzuki	Denso	0761x	SH7055	TF005	07 - RENESAS SH705x (TM007)		E121
	262	Suzuki	Denso	1.3 MT	SH7055	TF005	07 - RENESAS SH705x (TM007)		E121
	316	Suzuki	Denso	1.6 MT	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
	533	Suzuki	Denso	32920-01H000	SH7054	TF005	07 - RENESAS SH705x (TM007)		E121
New	853	Suzuki	Denso	32920-04KA0		TF009	17 - RENESAS M32R (TM017)		E121
	528	Suzuki	Denso	32920-08J11	M32R196	TF009	17 - RENESAS M32R (TM017)		E121
	523	Suzuki	Denso	32920-21Hxxx	M32R196	TF009	17 - RENESAS M32R (TM017)		E121
	672	Suzuki	Denso	32920-24FXX	SH7054	TF005	07 - RENESAS SH705x (TM007)		E121
	526	Suzuki	Denso	32920-30G00	SH7054	TF005	07 - RENESAS SH705x (TM007)		E121
	822	Suzuki	Denso	32920-31J00	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
	557	Suzuki	Denso	3C3/2C0-8591A-XX	SH7054	TF005	07 - RENESAS SH705x (TM007)		E121
	364	Suzuki	IAW Marelli	8DS	MPC5565	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		E101
	9	Suzuki	IAW Marelli	UZ13DT	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E101
	616	Suzuki	Mitsubishi	33920-93J40	MH5xxxF	TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)		NO CHECKSUM
New	865	Suzuki	Mitsubishi	33920-98JF0	MH8102F	TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)		E121
	489	Suzuki	Mitsubishi	E6T13xxx	MH7203	TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)		NO CHECKSUM
	369	Suzuki	Mitsubishi	E6T172	MH8305F	TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)		E121
	355	Suzuki	Mitsubishi	E6T900 M0	MH8102F	TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)		E121
	348	Suzuki / GM Group / Opel	IAW Marelli	MJD 602.04	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E101
	254	Suzuki Outboard	Melco		MH7203F	TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)		NO CHECKSUM
	477	Suzuki Outboard	Melco		MH7202	TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)		NO CHECKSUM
	15	Tata	Delphi		MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E65
	636	Tata	IAW Marelli	MJD 602	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E101
	404	Tata Trucks (Cummins)	Motorola	CM876	MPC565 / MPC566	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		NO CHECKSUM
	722	Tigercat (Cummins)	Motorola	CM850	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		NO CHECKSUM

New/Upg	PLUGIN ID	VEHICLE MANUFACTURER / COSTRUTTORE	ECU BRAND / MARCA ECU	ECU MODEL / MODELLO ECU	CPU (PROCESSOR) / CPU (PROCESSORE)	CPU GROUP / GRUPPO CPU	CPU APPLICATION (SPEC.) / FAMIGLIA CPU (SPEC.)	OBDDI PATCH / SBLOCCO OBDDI	CHECKSUM MOD. / MOD. CHECKSUM
	13	Toyota	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E52
	195	Toyota	Bosch	EDC17CP07	TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	775	Toyota	Bosch	EDC17C73	TC1793	TF003	39 - INFINEON TRICORE BOSCH MEDC17 GPT TOYOTA		E94
	356	Toyota	Bosch	ME7.9.5	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E97
	54	Toyota	Bosch	ME7.9.51	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E97
	838	Toyota	Denso	21175-2540	76F0038AGD	TF010	36 - NEC NBD		E151
	759	Toyota	Denso	175822-666	76F0040GD	TF010	36 - NEC NBD		E151
	776	Toyota	Denso	175822-737	76F0039GD	TF010	36 - NEC NBD		E151
	777	Toyota	Denso	175822-737	76F0038GD	TF010	36 - NEC NBD		E151
	758	Toyota	Denso	175822-762	76F0038AGD	TF010	36 - NEC NBD		E151
	769	Toyota	Denso	175822-762	76F0039GD	TF010	36 - NEC NBD		E151
	746	Toyota	Denso	175822-773	76F0038AGD	TF010	36 - NEC NBD		E151
	764	Toyota	Denso	175822-773	76F0038GD	TF010	36 - NEC NBD		E151
	770	Toyota	Denso	175822-773	76F0039AGD	TF010	36 - NEC NBD		E151
	783	Toyota	Denso	175822-773	76F0039GD	TF010	36 - NEC NBD		E151
	755	Toyota	Denso	175822-887	76F0038AGD	TF010	36 - NEC NBD		E151
	782	Toyota	Denso	175822-887	76F0039GD	TF010	36 - NEC NBD		E151
	774	Toyota	Denso	175822-887	76F0040GD	TF010	36 - NEC NBD		E151
	795	Toyota	Denso	175822-887	76F0040AGD	TF010	36 - NEC NBD		E151
	821	Toyota	Denso	175822-887	76F0040AGD	TF010	36 - NEC NBD		E151
	765	Toyota	Denso	176522-762	76F0039AGD	TF010	36 - NEC NBD		E151
	766	Toyota	Denso	176622-762	76F0038GD	TF010	36 - NEC NBD		E151
	763	Toyota	Denso	211941-37910830	76F0038AGD	TF010	36 - NEC NBD		E151
New	861	Toyota	Denso	211941-45900930	76F0038AGD	TF010	36 - NEC NBD		E151
	815	Toyota	Denso	275036-0360	76F0038GD	TF010	36 - NEC NBD		E151
	752	Toyota	Denso	275036-1152	76F0039GD	TF010	36 - NEC NBD		E151
	753	Toyota	Denso	275036-1152	76F0038AGD	TF010	36 - NEC NBD		E151
	778	Toyota	Denso	275036-1152	76F0038AGD	TF010	36 - NEC NBD		E151
	814	Toyota	Denso	275036-1152	76F0039GD	TF010	36 - NEC NBD		E151
	840	Toyota	Denso	275036-1152	76F0038GD	TF010	36 - NEC NBD		E151
	846	Toyota	Denso	275036-1470	76F0038GD	TF010	36 - NEC NBD		E151
	760	Toyota	Denso	275036-2110	76F0038AGD	TF010	36 - NEC NBD		E151
	843	Toyota	Denso	275036-2440	76F0038AGD	TF010	36 - NEC NBD		E151
	796	Toyota	Denso	275036-3410	76F0038GD	TF010	36 - NEC NBD		E151
New	857	Toyota	Denso	275036-3410	76F0070	TF010	36 - NEC NBD		E151
	761	Toyota	Denso	275036-3560	76F0070	TF010	36 - NEC NBD		E151
	806	Toyota	Denso	275036-4520	76F0038AGD	TF010	36 - NEC NBD		E151
	747	Toyota	Denso	275036-4820	76F0038AGD	TF010	36 - NEC NBD		E151
New	851	Toyota	Denso	275036-4820	76F0038AGD	TF010	36 - NEC NBD		E151
	779	Toyota	Denso	275036-5130	76F0070	TF010	36 - NEC NBD		E151
	801	Toyota	Denso	275036-5280	76F0085	TF010	36 - NEC NBD		E151
	839	Toyota	Denso	275036-5650	76F0085	TF010	36 - NEC NBD		E151
	812	Toyota	Denso	275036-6941	76F0039GD	TF010	36 - NEC NBD		E151
	798	Toyota	Denso	275036-7341	76F0040GD	TF010	36 - NEC NBD		E151
	797	Toyota	Denso	275036-8730	76F0038GD	TF010	36 - NEC NBD		E151
	781	Toyota	Denso	275036-9160	76F0038AGD	TF010	36 - NEC NBD		E151
New	855	Toyota	Denso	275036-9160	76F0039GD	TF010	36 - NEC NBD		E151
	754	Toyota	Denso	275036-9170	76F0038AGD	TF010	36 - NEC NBD		E151
	820	Toyota	Denso	275036-9170	76F0040GD	TF010	36 - NEC NBD		E151
	772	Toyota	Denso	275036-7780	76F0039GD	TF010	36 - NEC NBD		E151
	767	Toyota	Denso	275922-001	76F0070	TF010	36 - NEC NBD		E151
	762	Toyota	Denso	275922-022	76F0085	TF010	36 - NEC NBD		E151
	836	Toyota	Denso	275922-092	76F0070	TF010	36 - NEC NBD		E151
	771	Toyota	Denso	275922-473	76F0085	TF010	36 - NEC NBD		E151
	802	Toyota	Denso	275922-500	76F0085	TF010	36 - NEC NBD		E151
	841	Toyota	Denso	275922-532	76F0085	TF010	36 - NEC NBD		E151
	837	Toyota	Denso	275922-5920	76F0070	TF010	36 - NEC NBD		E151
	794	Toyota	Denso	275992-428	76F0070	TF010	36 - NEC NBD		E151
	2	VAG (VW Group)	Bosch	EDC16 U2.1	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	Patch (OBDDI Unlock)	E52
	96	VAG (VW Group)	Bosch	EDC16+ CP	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	Patch (OBDDI Unlock)	E67
	109	VAG (VW Group)	Bosch	EDC16+ CP	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	Patch (OBDDI Unlock)	E67
	67	VAG (VW Group)	Bosch	EDC16+ U34	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	Patch (OBDDI Unlock)	E67
	149	VAG (VW Group)	Bosch	EDC17 U01	TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	207	VAG (VW Group)	Bosch	EDC17 U05 external flash	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	199	VAG (VW Group)	Bosch	EDC17C46	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	Patch (OBDDI Unlock)	E94
	269	VAG (VW Group)	Bosch	EDC17C46	TC1767	TF003	13 - INFINEON TRICORE BOSCH MEDC17 TPROT8/10 VAG (TM013)	Patch (OBDDI Unlock)	E94
	420	VAG (VW Group)	Bosch	EDC17C54	TC1797	TF003	13 - INFINEON TRICORE BOSCH MEDC17 TPROT8/10 VAG (TM013)		E94
	675	VAG (VW Group)	Bosch	EDC17C64	TC1797	TF003	23 - INFINEON TRICORE BOSCH MEDC17 GPT VAG		E94
	705	VAG (VW Group)	Bosch	EDC17C74	TC1793	TF003	23 - INFINEON TRICORE BOSCH MEDC17 GPT VAG		E94
	126	VAG (VW Group)	Bosch	EDC17CP04	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	425	VAG (VW Group)	Bosch	EDC17CP14	TC1796	TF003	13 - INFINEON TRICORE BOSCH MEDC17 TPROT8/10 VAG (TM013)	Patch (OBDDI Unlock)	E94
	716	VAG (VW Group)	Bosch	EDC17CP14	TC1796	TF003	23 - INFINEON TRICORE BOSCH MEDC17 GPT VAG	Patch (OBDDI Unlock)	E94
	146	VAG (VW Group)	Bosch	EDC17CP14 external flash	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	Patch (OBDDI Unlock)	E94
	151	VAG (VW Group)	Bosch	EDC17CP14 internal flash	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	Patch (OBDDI Unlock)	E94
	665	VAG (VW Group)	Bosch	EDC17CP14 TPROT7.0 external flash	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	166	VAG (VW Group)	Bosch	EDC17CP14 USA ext. flash	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	Patch (OBDDI Unlock)	E94
	427	VAG (VW Group)	Bosch	EDC17CP20 (rom)	TC1796	TF003	13 - INFINEON TRICORE BOSCH MEDC17 TPROT8/10 VAG (TM013)		E94
	165	VAG (VW Group)	Bosch	EDC17CP20 external flash	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	187	VAG (VW Group)	Bosch	EDC17CP20 internal flash	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	162	VAG (VW Group)	Bosch	EDC17CP24 external flash	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	203	VAG (VW Group)	Bosch	EDC17CP44	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	268	VAG (VW Group)	Bosch	EDC17CP44	TC1797	TF003	13 - INFINEON TRICORE BOSCH MEDC17 TPROT8/10 VAG (TM013)		E94

New/Upg	PLUGIN ID	VEHICLE MANUFACTURER / COSTRUTTORE	ECU BRAND / MARCA ECU	ECU MODEL / MODELLO ECU	CPU (PROCESSOR) / CPU (PROCESSORE)	CPU GROUP / GRUPPO CPU	CPU APPLICATION (SPEC.) / FAMIGLIA CPU (SPEC.)	OBDDII PATCH / SBLOCCO OBDDII	CHECKSUM MOD. / MOD. CHECKSUM
	676	VAG (VW Group)	Bosch	EDC17CP44	TC1797	TF003	23 - INFINEON TRICORE BOSCH MEDC17 GPT VAG		E94
	739	VAG (VW Group)	Bosch	EDC17CP54	TC1793	TF003	23 - INFINEON TRICORE BOSCH MEDC17 GPT VAG		E94
	748	VAG (VW Group)	Bosch	EDC17CP74	TC1793	TF003	23 - INFINEON TRICORE BOSCH MEDC17 GPT VAG		E94
	50	VAG (VW Group)	Bosch	ME7.1.1	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E21/E42
	51	VAG (VW Group)	Bosch	ME7.1.1	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E21
	52	VAG (VW Group)	Bosch	ME7.1.1	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E84
	539	VAG (VW Group)	Bosch	ME7.1.1	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E84
	48	VAG (VW Group)	Bosch	ME7.5	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E21/E42
	53	VAG (VW Group)	Bosch	ME7.5	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E21
	49	VAG (VW Group)	Bosch	ME7.5.10	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E21
	186	VAG (VW Group)	Bosch	ME7.5.20 - ME7.5.30	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E42
	293	VAG (VW Group)	Bosch	MED17.1	TC1796	TF003	13 - INFINEON TRICORE BOSCH MEDC17 TPROT8/10 VAG (TM013)		E94
	723	VAG (VW Group)	Bosch	MED17.1	TC1796	TF003	23 - INFINEON TRICORE BOSCH MEDC17 GPT VAG		E94
	168	VAG (VW Group)	Bosch	MED17.1 (irrom)	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	218	VAG (VW Group)	Bosch	MED17.1 (xrom)	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	266	VAG (VW Group)	Bosch	MED17.1.1	TC1796	TF003	13 - INFINEON TRICORE BOSCH MEDC17 TPROT8/10 VAG (TM013)		E94
	792	VAG (VW Group)	Bosch	MED17.1.1	TC1796	TF003	13 - INFINEON TRICORE BOSCH MEDC17 TPROT8/10 VAG (TM013)		E94
	707	VAG (VW Group)	Bosch	MED17.1.1	TC1797	TF003	23 - INFINEON TRICORE BOSCH MEDC17 GPT VAG		E94
	378	VAG (VW Group)	Bosch	MED17.1.6	TC1797	TF003	13 - INFINEON TRICORE BOSCH MEDC17 TPROT8/10 VAG (TM013)		E94
	690	VAG (VW Group)	Bosch	MED17.1.6	TC1797	TF003	23 - INFINEON TRICORE BOSCH MEDC17 GPT VAG		E94
	800	VAG (VW Group)	Bosch	MED17.1.21	TC1793	TF003	23 - INFINEON TRICORE BOSCH MEDC17 GPT VAG		E94
	128	VAG (VW Group)	Bosch	MED17.5	TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	472	VAG (VW Group)	Bosch	MED17.5	TC1767	TF003	13 - INFINEON TRICORE BOSCH MEDC17 TPROT8/10 VAG (TM013)		E94
	147	VAG (VW Group)	Bosch	MED17.5.1	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	267	VAG (VW Group)	Bosch	MED17.5.1	TC1766	TF003	13 - INFINEON TRICORE BOSCH MEDC17 TPROT8/10 VAG (TM013)		E94
	435	VAG (VW Group)	Bosch	MED17.5.10	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E21/E42
	689	VAG (VW Group)	Bosch	MED17.5.2	TC1767	TF003	23 - INFINEON TRICORE BOSCH MEDC17 GPT VAG		E94
	334	VAG (VW Group)	Bosch	MED17.5.2 (irrom)	TC1767	TF003	13 - INFINEON TRICORE BOSCH MEDC17 TPROT8/10 VAG (TM013)		E94
	179	VAG (VW Group)	Bosch	MED17.5.20	TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	695	VAG (VW Group)	Bosch	MED17.5.21	TC1782	TF003	23 - INFINEON TRICORE BOSCH MEDC17 GPT VAG		E94
	697	VAG (VW Group)	Bosch	MED17.5.24	TC1724	TF003	23 - INFINEON TRICORE BOSCH MEDC17 GPT VAG		E94
	696	VAG (VW Group)	Bosch	MED17.5.5	TC1767	TF003	23 - INFINEON TRICORE BOSCH MEDC17 GPT VAG		E94
	715	VAG (VW Group)	Bosch	MED17.5.5	TC1762 / TC1766	TF003	23 - INFINEON TRICORE BOSCH MEDC17 GPT VAG		E94
	358	VAG (VW Group)	Bosch	MED17.5.6	TC1767	TF003	13 - INFINEON TRICORE BOSCH MEDC17 TPROT8/10 VAG (TM013)		E94
	780	VAG (VW Group)	Bosch	MED17.5.6	TC1767	TF003	23 - INFINEON TRICORE BOSCH MEDC17 GPT VAG		E94
	64	VAG (VW Group)	Bosch	MED9.1/MED9.5/MED9.5.10	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E58/E85
	390	VAG (VW Group)	IAW Marelli	44F	ST10F269	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
	183	VAG (VW Group)	IAW Marelli	44VP	ST10F269	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
	835	VAG (VW Group)	IAW Marelli	44V	MC68300	TF007	09 - MOTOROLA MC68xxx (TM009)		E101
	184	VAG (VW Group)	IAW Marelli	4BV	ST10F280	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
	674	VAG (VW Group)	IAW Marelli	4CW	ST10F280	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
	374	VAG (VW Group)	IAW Marelli	4GV	ST10F296	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
	185	VAG (VW Group)	IAW Marelli	4HV	ST10F296	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
	173	VAG (VW Group)	IAW Marelli	4TV	ST10F280	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
	513	VAG (VW Group)	Siemens VDO	PCR2.1	ST95640	TF003	18 - INFINEON TRICORE SIEMENS PCR2.1/SIMOS8.xx VAG (TM018)	Patch (OBDDII Unlock)	E131
	75	VAG (VW Group)	Siemens VDO	SIMOS 5WP4 PPD1.x	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E69
	174	VAG (VW Group)	Siemens VDO	SIMOS 6.2 6.3	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E69
	214	VAG (VW Group)	Siemens VDO	SIMOS 6.2 6.3	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E69
	512	VAG (VW Group)	Siemens VDO	SIMOS 8.x	ST95640	TF003	18 - INFINEON TRICORE SIEMENS PCR2.1/SIMOS8.xx VAG (TM018)	Patch (OBDDII Unlock)	E134
	89	Valtra Sisu (AGCO Group)	Bosch	EDC7U31	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
	342	Volkswagen Truck	Bosch	EDC1C68	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E52
	58	Volkswagen Truck	Bosch	EDC7C1	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E52
	93	Volkswagen Truck (Cummins)	Motorola	CM850	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		NO CHECKSUM
	68	Volvo	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
	113	Volvo	Bosch	EDC16+	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
	158	Volvo	Bosch	EDC17CP22	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	681	Volvo	Bosch	EDC17CP48	TC1797	TF003	24 - INFINEON TRICORE BOSCH MEDC17 GPT VOLVO		E94
	743	Volvo	Bosch	EDC17CP68	TC1797	TF003	24 - INFINEON TRICORE BOSCH MEDC17 GPT VOLVO		E94
	624	Volvo	Bosch	ME7 (AM29F400)	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E46
	325	Volvo	Bosch	ME7 (AM29F800)	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E46
	626	Volvo	Bosch	ME7 (AM29F800)	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E46
	73	Volvo	Bosch	ME9+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E70
	421	Volvo	Denso	079700-9xxx	SH7058	TF005	07 - RENESAS SH705x (TM007)		NO CHECKSUM
	326	Volvo	Denso	2.4	SH7058	TF005	07 - RENESAS SH705x (TM007)		NO CHECKSUM
	499	Volvo	Denso	HP.2	SH7055	TF005	07 - RENESAS SH705x (TM007)		NO CHECKSUM
	399	Volvo Penta	Bosch	EDC17CP22	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
	357	Volvo Power Generator	TRW Motorola	EMS2	MPC565 / MPC566	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E80
	138	Volvo Truck / Renault Truck	TRW Motorola	EMS2	MPC565 / MPC566	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E80
	246	Volvo Truck / Renault Truck	TRW Motorola	EMS2 (EURO4/EURO5 version)	MPC5554	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		E80
	59	Volvo Truck / Volvo Penta	Bosch	EDC7C1	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E52
	788	Volvo Truck	Bosch	EDC7U31	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67/E133
	433	Weichai Truck (Weichai engines)	Bosch	EDC7 UC31	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
	612	XCMG	Bosch	EDC7 U31	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67/E133
	559	Yale	Sagem	S3000	SH7055	TF005	07 - RENESAS SH705x (TM007)		E73
	562	Yamaha	Denso	13S-8591A-00 MICRO 1	SH7054	TF005	07 - RENESAS SH705x (TM007)		E121
	563	Yamaha	Denso	13S-8591A-00 MICRO 2	SH7054	TF005	07 - RENESAS SH705x (TM007)		E121
	555	Yamaha	Denso	14B-8591A-XX MICRO 1	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
	556	Yamaha	Denso	14B-8591A-XX MICRO 2	SH7054	TF005	07 - RENESAS SH705x (TM007)		E121
	646	Yamaha	Denso	1RC-8591A-XX	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
New	848	Yamaha	Denso	1WS-8591A-XX	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
	834	Yamaha	Denso	2RC-8591A-XX	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
New	849	Yamaha	Denso	39P-8591A-XX	SH7055	TF005	07 - RENESAS SH705x (TM007)		E121

	PLUGIN ID	VEHICLE MANUFACTURER / COSTRUTTORE	ECU BRAND / MARCA ECU	ECU MODEL / MODELLO ECU	CPU (PROCESSOR) / CPU (PROCESSORE)	CPU GROUP / GRUPPO CPU	CPU APPLICATION (SPEC.) / FAMIGLIA CPU (SPEC.)	OBDII PATCH/ SBLOCCO OBDII	CHECKSUM MOD./ MOD. CHECKSUM
	553	Yamaha	Denso	4C8-8591A-XX MICRO 1	SH7054	TF005	07 - RENESAS SH705x (TM007)		E121
	554	Yamaha	Denso	4C8-8591A-XX MICRO 2	SH7054	TF005	07 - RENESAS SH705x (TM007)		E121
	574	Yamaha	Melco	F8T9487x	MH7203	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		NO CHECKSUM
New	866	Yamaha	Mitsubishi	SSL-8591A-XX	MH7203	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		NO CHECKSUM
	842	Yamaha	Mitsubishi	5YU-8591A-XX	MH5XXXF	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		NO CHECKSUM
	859	Yamaha	Mitsubishi	63P-8591A-XX	MH8102F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		NO CHECKSUM
New	850	Yamaha	Mitsubishi	68V-8591A-XX	MH8102F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		NO CHECKSUM
	631	Yamaha	Mitsubishi	6D9-8591A-14	MH8102F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		E121
	634	Yamaha	Mitsubishi	F8T81X	MH5XXXF	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		NO CHECKSUM
	686	Yamaha	Mitsubishi	F8T820XXX	MH5XXXF	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		NO CHECKSUM
	664	Yamaha	Mitsubishi	F8T84475	MH8102F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		E121
	284	Yamaha	Mitsubishi	FX-SHO	MH8305F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		E121
	656	Yanmar	Bosch	EDC17CV54	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94